

14
3



FORM-D1
(Chapter 2, Para 2.7.1/2.7.3)

COMPLETION CUM OCCUPANCY CERTIFICATE

Name of the Authority East Delhi Municipal Corporation

Date 28/11/2019

File No./Plan No. 10069611

To,
Mr. RISHABH EDUCATIONAL SOCIETY REG

With reference to your notice of completion dated 30/11/2005, I hereby certify that the building as per description below and certified plans of RISHABH PUBLIC SCHOOL, POCKET IV, MAYUR VIHAR PH - I, NEW DELHI whose LOP and Bldg. plans were sanctioned vide letter No. 10069611 dated and completion certificate as approved by DUAC/DFS and other statutory bodies, the NOC has been approved on 08/11/2019. The site has been inspected with reference to Building Bye-Laws, Master Plan Delhi provisions, hygienic and sanitary conditions inside and in the surroundings and is declared fit for occupation.

The approving authority approves Architectural Drawings/Development Control norms with respect to the Building Bye Laws and Master Plan provisions only. The technical drawings/documents submitted by the owner/consultant/Architect/Engineer/Structural Engineer/Landscape Architect /Urban Designer/Engineer for Utility Services are considered as part of the records/information supporting the building permit only. The responsibility of the correctness of information/application of technical provisions fully vests with the owner/consultant/ Architect/Engineer/Structural Engineer/Landscape Architect /Urban Designer/Engineer for Utility Services and shall be liable as per laws.

The structural stability of the building is based on the certificate given jointly by the Owner/Architect/Structural Engineer along with one set of Structural Drawings, incorporating therein the provisions of Structural Safety as specified in the relevant prevailing IS Codes/Standards/Guidelines stated in the Government of India Notification bearing No.SO-248(E) dated 21.3.2001 and clause 9.1, 9.2.1, 9.2.2 and Annexure VII of this Bye Laws.. For the fire-safety the same has been based on the clearance given by the Chief Fire Officer, Government of NCT of Delhi. The Authority/Local Body shall not have any responsibility for any loss caused to the building from any natural hazard / calamity.

Completion Certificate is issued for Plot No. MIDDLE SCHOOL as per enclosed drawings.

S.No	Floor	Remarks
1	Ground Floor	No entry found for any floors (*auto-approved case)

For R.E.
[Signature]
[Signature]
RISHABH PUBLIC SCHOOL

Given Below is the remarks provided by concerned authority

Approved as proposed.

Yours Faithfully

East Delhi Municipal Corporation
Executive Engineer

दिल्ली नगर निगम



MUNICIPAL CORPORATION OF DELHI

Office of The Executive Engineer(M)-IV
School Block, Shakar pu, Delhi-92

26/5/10
Dated


No. EE(M)-IV/AE-II/2010-11/ **D233**


To,
Rishabh Educational Society (Regd.)
Pkt-IV, Mayur Vihar Phase-I
Delhi-110091.

Subject: Structural Stability Certificate in Respect of Rishabh Educational
Society (Regd.) Pkt-IV, Mayur Vihar Phase-I Delhi-110091 (School Bldg.)

Dear sir,

Kindly refer to your letter no. Nil Dated 04.11.09 regarding Structural Stability Certificate As per structural stability certificate issued by Sh. J.P. Singh Architect (CA/87/11135) for Swait Arch. E-1082, Sarswati Vihar, Pitampura, Delhi Stating that the building of Rishabh Educational Society at Pkt-IV Mayur Ph-I, Delhi-110091 is structurally safe and sound. The undersigned with J.E also made a visual inspection on Dt. 04.05.10 and found the Bldg. is structurally safe & stable and there is no imminent danger to bldg. at present. The given certificate is not for any unauthorized construction made and bear the other loads and also on ownership of the land. This is subject to the fire safety certificate issued by the Fire Deptt.


Assistant Engineer-II
M.C.D

For RISHABH EDUCATIONAL SOCIETY

Authorized Signatory